



Carpet Pad Adhesive

The Professional's Formula For Success when installing carpet pad.

APPLICATIONS:

- USE ONLY FOR:
All carpet pads, including jute, hair, rubber, urethane, or rebond. Residential use only.
- BONDS TO: Concrete, underlayments, wood substrates, and existing resilient on all grade levels as recommended by the carpet pad manufacturer.

TECHNICAL DATA:

- Base: Water-based/rubber-resin
- Color: Beige
- Taggant Color: Fire-orange
- Next Generation: Solvent-free, nonflammable
- Open Time: None
- Working Time: 10 minutes
NOTE: Working times vary based on job conditions, substrates, temperature and humidity.

- Size: Gallon
- Shipping Unit: 4 gallons/ctn
- Weight Per Gallon: 10.3 lbs
- Quantity Per Pallet: 40 ctns
- Shelf Life: One year if not opened
- Freeze-Thaw Stable: Keep from freezing
- Coverage: 500-600 lin ft/gal at 1/8" bead

DIRECTIONS:

Refer to carpet pad manufacturer's specific recommendations. Condition the area to be installed, adhesive and flooring at 65°F (18°C) or above for 48 hours before, during and 48 hours after installation. Floor must be sound, smooth, dry, clean and free of excessive moisture or alkali. Remove dirt, wax, loose paint and all other foreign matter that would interfere with a good bond such as curing agents and sealers.

- Open flip-top lid. Apply adhesive 3-4 inches away from each wall, in criss-cross pattern, the full length of all pad seams. Slight hand pressure on side of container will help regulate flow.
- Adhesive should be spread in an even film. A scrap of carpet can be used to help even the film.
- Allow the adhesive to set for 1-2 minutes, then lay pad immediately. Walk pad into adhesive, making certain to apply pressure at the seams.

WARRANTY: We warrant that HENRY 377 will not break down or lose its cohesive strength due to a manufacturing or formulation defect for 10 years from the date of installation, if used for its stated purpose and applied in accordance to the instructions, subject to certain exclusions and limitations set forth in the warranty.

WARNINGS: Carefully read and follow all cautions and warnings on the product label. Refer to the Material Safety Data Sheet for additional product information.

CLEANUP: Wet Adhesive: Clean, white cloth dampened with soapy water.
Dried Adhesive: Clean, white cloth dampened with mineral spirits; carefully following warnings on the container.

UPC INFORMATION: Gallon: 0-81833-37740-8

The W. W. Henry Company
400 Ardex Park Drive
Aliquippa, PA 15001
Technical Support: 1-800-232-4832
Internet: wwhenry.com

THE PROFESSIONAL'S FORMULA FOR SUCCESS™